



The main jet needs an oversize driver to fit the slot as well. Stromberg cautions that care should be taken not to damage the slot so as not to affect the flow. The 45 is the size for the C-85 only.



P78x

In order to properly torque the nozzle, this box/open end wrench was modified to fit the nozzle on one end and the torque wrench socket end on the other.



This is a standard accessory for socket wrenches, and its thickness/breadth work best to fit the slots of the main jet and seats.

